## REPORT

## TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS

RESEARCH

DEVELOPMENT

TESTING

DOUGLAS AIRCRAFT COMPANY

**CLIENT** 

Internal Mail Code 211-40

3855 Lakewood Blvd.

Long Beach, CA 90846

**SAMPLE** 

Attention: Robert Tomkp

Monthly Storm Drain Inspection April, 1989

INVESTIGATION. No.: T & M-23465-C

As requested by the CRWQCB for NPDES permit numbers CA0001406 and CA0001414



FRANKLIN AVENUE TUSTIN, CALIFORNIA 92680 AREA CODE 714 • 730-6239 AREA CODE 213 . 225-1564 CABLE: TRUELABS

DATE

May 15, 1989

RECEIVED

April 28, 1989

LABORATORY NO. 32534/32545

## RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on April 28, 1989, at the Douglas, Long Beach (003) and Torrance facilities. The discharge was tested for flow rate, pH, and temperature. The results are as follows:

Sample I.D.	<u>Date</u>	Time	FLow-gpd	Temp OF	pH Units
Long Beach (003)	4/28/89	10:45	73,180	68	8.4
Torrance	4/27/89	10:53	1,184	62	7.6

Respectfully submitted,

TRUESDAIL LABORATORIES, INC.

Luis Perez, Supervisor Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.